

WELDING - REQUIRED PERSONAL PROTECTIVE EQUIPMENT

Activity	 Safety Glasses	 Ear Plugs	 Leather Gloves	 Boots	 Burning Goggles	Other
Grinding	X	X	X	X		
Handling scrap steel			X	X		
Cutting metal	X		X	X		
Use of high pressure air arc	X	X		X		Heavy Clothing
Arc or gas welding			X	X	X	Heavy Clothing
Using electrical equipment while floor is wet/electrocution	Do not work in this condition					

**Compatibility Report for PPE Matrix - Art
Department.xls
Run on 5/24/2011 12:08**

The following features in this workbook are not supported by earlier versions of Excel. These features may be lost or degraded when you save this workbook in an earlier file format.

Significant loss of functionality

**# of
occurrences**

Any effects on this object will be removed. Any text that overflows the boundaries of this graphic will appear clipped.

1

['Sheet1'!A1:AH360](#)

This object will no longer be editable.

7

['Sheet1'!A1:AH360](#)

Minor loss of fidelity

Some cells or styles in this workbook contain formatting that is not supported by the selected file format. These formats will be converted to the closest format available.

7